



## Contractor job sheet

Property: Burgh House Apartment 15 Ings Lane, Skellow, Doncaster, DN6 8QU.

Landlord: Mr Mark Richards

Tenant: Miss Paige Dilks

Job ID: 7213

Job title: Faulty Heat Detector

Description: Issue with heat detector in kitchen & extractor in bathroom

Reported on: 01/12/2022

Recorded by: Laura Green

Images:

Images are only available in email format

Scheduled on:

Contractor: Glynn Walker

Address: 25 York Street, New Rossington, Doncaster, DN11 0TF.

Telephone:

Mobile: 07889174819

Work:

Email:

Call:

01 302 867888

Fax: 01302 868188

[www.3keysproperty.co.uk](http://www.3keysproperty.co.uk)